

C of C

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450, on

Kathi Howard 3-11-05  
Kathi Howard Date



## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Serial No.: 09/483,248  
Filed: January 14, 2000  
Patent No.: 6,746,851 B1  
Issued: June 8, 2004  
Applicant(s): Ken K. Tseung, Glenn Takayama, Norman K. Rhett, and Mark V. Corl  
Title: METHOD FOR AUTOMATED STAINING OF SPECIMEN SLIDES

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

Certificate  
MAR 16 2005  
of Correction

ATTN: DECISION AND CERTIFICATE OF CORRECTION  
BRANCH OF THE PATENT ISSUE DIVISION

### **REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR PTO MISTAKE (37 CFR §1.322 (a))**

Sir:

Attached in duplicate form, is Form PTO-1050, with at least one copy being suitable for printing. The errors which appear in the Form PTO-1050 were typographical errors which occurred through the fault of the U.S. Patent and Trademark Office ("PTO").

The exact column and line number where the errors are shown in the patent are as follows:

Preamble, "OTHER PUBLICATIONS" reads, "Biotex Solutions (1993), Techmate 500<sup>TM</sup> & Techmate 1000<sup>TM</sup> Automated Immunostaining System." and should read - Biotek Solutions (1993), Techmate 500<sup>TM</sup> & Techmate 1000<sup>TM</sup> Automated Immunostaining System. -.

Column 8, Claim 2 lines 10-11 read "...not initiating the staining protocol when said first identifier is not the same as said second identifier..." and should read – not initiating the staining protocol when said first identifier is not the same as said second identifier... –.

Please send the certificate to:

Donald F. Frei, Esq.  
Wood, Herron & Evans, L.L.P.  
2700 Carew Tower  
Cincinnati, Ohio 45202

If there is any charge or credit due, please use Deposit Account No. 23-3000.

Respectfully submitted,

WOOD, HERRON & EVANS, L.L.P.

By:



Donald F. Frei, Reg. No. 21,190

WOOD, HERRON & EVANS, L.L.P.  
2700 Carew Tower  
Cincinnati, Ohio 45202  
(513) 241-2324

Staple  
Here  
Only

Printer's  
Trim  
Line

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : 6,746,851 B1

DATED : June 8, 2004

INVENTOR(S) : Ken K. Tseung, Glenn Takayama, Norman K. Rhett, and Mark V. Corl

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Preamble, "OTHER PUBLICATIONS" reads, "Biotex Solutions (1993), Techmate 500<sup>TM</sup> & Techmate 1000<sup>TM</sup> Automated Immunostaining System." and should read – Bioteck Solutions (1993), Techmate 500<sup>TM</sup> & Techmate 1000<sup>TM</sup> Automated Immunostaining System. –.

Column 8, Claim 2 lines 10-11 read "...not initiating the staining protocol when said first identifier is not the same as said second identifier..." and should read – not initiating the staining protocol when said first identifier is not the same as said second identifier... –.

-----  
MAILING ADDRESS OF SENDER:

Wood, Herron & Evans, L.L.P.  
2700 Carew Tower  
441 Vine Street  
Cincinnati, OH 45202-2917

PATENT NO. 6,746,851  
No. of add'l copies

@ 50¢ per page: \_\_\_\_\_

MAR 17 2005

Staple  
Here  
Only

Printer's  
Trim  
Line

UNITED STATES PATENT AND TRADEMARK OFFICE

**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,746,851 *B1*

DATED : June 8, 2004

INVENTOR(S) : Ken K. Tseung, Glenn Takayama, Norman K. Rhett, and Mark V. Corl

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Preamble, "OTHER PUBLICATIONS" reads, "Biotex Solutions (1993), Techmate 500<sup>TM</sup> & Techmate 1000<sup>TM</sup> Automated Immunostaining System." and should read – Biotek Solutions (1993), Techmate 500<sup>TM</sup> & Techmate 1000<sup>TM</sup> Automated Immunostaining System. –.

Column 8, Claim 2 lines 10-11 read "...not initiating the staining protocol when said first identifier is not the same as said second identifier..." and should read – not initiating the staining protocol when said first identifier is not the same as said second identifier... –.

-----  
MAILING ADDRESS OF SENDER:

Wood, Herron & Evans, L.L.P.  
2700 Carew Tower  
441 Vine Street  
Cincinnati, OH 45202-2917

PATENT NO. 6,746,851  
No. of add'l copies \_\_\_\_\_

@ 50¢ per page: \_\_\_\_\_

MAR 17 2005